

Attention: Important Safety Alert!

Product: Playworld Stainless Steel Lightning Slides and Double Lightning Slides

Playworld Systems, Inc. has identified a potential safety issue regarding its Stainless Steel Lightning Slides and Double Lightning Slides sold between October 2000 and October 20, 2016.

Our records show that you purchased and received one or more Playworld Stainless Steel Lightning Slides and/or Double Lightning Slides in that timeframe. For identification purposes, the stainless steel slides were manufactured by Playworld, and are depicted below. [Note: Photos are for representation of the stainless steel slide. The slide barrier may be different in your application.]





Lightning Slide- single bedway slide

Double Lightning Slide - double bedway slide

Playworld has received a recent report that a child's little finger was amputated while using a Lightning Slide. The welds connecting the slide bedway (seating area of slide) and slide sidewalls (vertical panels welded to slide seating area) separated, leaving a sharp gap between the bedway and sidewalls. See photo of weld separation and gap below.



Arrow points to separated weld and gap between bedway and sidewall.



Please locate and identify your Playworld Stainless Steel Lightning Slides and Double Lightning Slides delivered to you on Playworld Customer Order No. ______, and take the following immediate action:

Using the attached inspection instructions and pass/fail criteria, immediately inspect Playworld Stainless Steel Lightning Slides and Double Lightning Slides.

If the slides fail and require removal, barricade the slide openings to prevent inadvertent falls from the platform and immediately contact Playworld for a free temporary platform barrier until a replacement slide can be shipped.

If slides pass and do not exhibit weld failures and separations between the bedway and sidewalls, continue to monitor the slides and inspect them as instructed on a weekly basis, until you receive further notice from Playworld.

If you have questions or require assistance, please contact Playworld by dialing 1-800-233-8404 or email your questions to info@playworld.com. We sincerely regret and apologize for any inconvenience caused by this product issue.

Yours Sincerely

Darryl Rarich Risk Manager